VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3548	DATE	March 31, 2015		
MANUFACTURER	SUZUKI MOTOR CORPORATION				
DESCRIPTION OF DEFECT	Grease applied at the contact point of the ignition switch may carbonize with heat repeatedly generated from arc discharge when the travelling side leaves from the fixed side at the contact point, due to the very grease being improper for the contact point. If the vehicle is used continuously as it is, the grease can make smoke due to heat from unexpected conduction of the switch with grease deterioration of insulation performance and abrasion powder accumulated around the contact point. In the worst case a fire might be induced.				

TYPE	COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLES
GF-MA63S	WAGON R	WAGON R PLUS	1999~2000	26,439
LA-MA64S		WAGON R SOLIO	2000~2002	10,784
LA-MA34S			2000~2005	26,441
UA-MA34S			2003~2005	12,383
DBA-MA34S	SOLIO		2005~2010	13,667
ABA-MA34S				4,458

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GF-ME63S		2000	129
LA-ME64S		2001~2002	90
LA-ME34S	MW	2001~2003	1,191
DBA-ME34S		2005 - 2010	25,292
ABA-ME34S		2005~2010	4,881
		TOTAL	125,755