CAMPAIGN No.	4202	DATE	22/2/2018		
MANUFACTURER	UD Trucks Corporation				
DESCRIPTION OF DEFECT	adjustment device using air susper down repeatedly for loading and of excessive contact surface pressure the vehicle is keep operated under the piston ring of the shock absorbed generated heat. With regards to the braking system some of the fastening torque for the condition, the plug and/or other condition, the plug and/or other condition, the plug and the tothe brake chamber, the vehicle Due to improper plating pretreatm front-axle right tie rod end, the stream of the condition of the plug and the stream of the plug and t	e Heavy-Duty Trucks, priate piston structure for shock absorber which is mounted to the vehicle with height vice using air suspensions, when a vehicle is lifted up to its maximum height and lowered ly for loading and other activities, the inside of the cylinder may become damaged by the act surface pressure generated by lateral force between the piston groove and the cylinder. If eep operated under this condition, there might be some metal piece staying and fixing into of the shock absorber, that may cause the shock absorber bend or breakage. In the worst the shock absorber may interfere with the tire then burst, or may cause a risk of fire due to the braking system, due to improper assembly process of front axle's brake chambers, stening torque for the closing plugs, testing nipples and brake hose connecting parts to for nipples and hoses) may be insufficient. If the vehicle is keep operated under this bolug and/or other connecting parts might become loose and cause air leakage. In the works or the test nipple may become detached from its original position and discontinued air supply namber, the vehicle's braking force may have a risk to be reduced. The replating pretreatment (acid cleaning) process for the fixing clamp fastening bolt of the frontitie rod end, the strength for the bolt may become deteriorated by hydrogen embrittlement. If thinues operation under this condition, the fastening bolt may be broken and cause backlash and. In the worst case, the tie rod tube might be broken and the vehicle might have a risk of			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5BA	Quon	2017-2018	39	① 39 ② 10
2PG-CD5BL	Quon	2017-2018	3	② 3
2PG-CD5CA	Quon	2017-2018	947	① 947 ② 231
2PG-CD5CL	Quon	2017	12	② 12
2PG-CG5BA	Quon	2017-2018	6	① 6 ② 3 ③ 2
2PG-CG5CA	Quon	2017-2018	1502	③ 2 ① 1502 ② 402 ③ 333
2PG-CG5CE	Quon	2018	1	① 1
2PG-CG5CL	Quon	2017	29	② 22 ③ 13
2PG-CW5AL	Quon	2017	127	② 127
2PG-CW5BL	Quon	2017	28	② 28
2PG-CW5CA	Quon	2017-2018	56	① 56 ② 21
2PG-CW5CL	Quon	2017	29	② 29
2PG-CX5BA	Quon	2017-2018	20	① 20 ② 6
2PG-CX5BL	Quon	2017	4	2 4
2PG-GK5AAB	Quon	2017-2018	275	① 275 ② 45
2PG-GK5AAD	Quon	2017-2018	66	① 66 ② 23
2PG-GK5AAE	Quon	2017	1	① 1 ② 1
		TOTAL	3145	① 2913 ② 967 ③ 348