VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	外-2937	DATE	October 29. 2019			
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.					
DESCRIPTION OF DEFECT	① In the forward and backward gear of agricultural tractor, the shift fork interfere with the collar due to variations in the dimensional tolerances. For this reason, if the use is continued as it is, the fork may be worn, and in the worst case, the fork may be damaged and the forward / reverse gear cannot be switched.					
	retainer is insufficient holds the ring gear is i damaged by a load at	because the streng nappropriate. For the the time of shifting,	I tractor, the strength of the th design of the retainer that his reason, the retainer is , and in the worst case, mesh properly and cannot			
	③ In the transmission gear of agricultural tractor, the selection of the planetary carrier bearing is inappropriate and the strength of the bearing is insufficient. Therefore, the bearing may be damaged by a load at the time of shifting, and in the worst case, there is a possibility that the gear does not mesh properly and cannot run.					
	structure of the valve i may be mixed into the	s inappropriate, so solenoid valve. For s not operate correc	of agricultural tractor, the that dust in hydraulic oil r this reason, the solenoid ctly, and in the worst case, mally.			
	some valve housings I manufacturing process in the worst case, the	have a cast hole du s. For this reason, o hydraulic pressure	oil leaks in the housing, and			
	piston may wear durin that controls the hydra	g gear shifting beca ulic pressure is ina ulic pressure canno	icultural tractor, the cam and ause the shape of the cam ppropriate. Therefore, in the t be controlled correctly, and avel normally.			
	gear bearings is inapp insufficient. For this re	e selection of the horographic series and the st ason, the bearing is and in the worst ca	ousing assembly and idler rength of the bearings is s damaged by a load applied se, there is a possibility that			
	of the clutch seal for the the strength of the seadamaged by a load at	ne high speed side al is insufficient. For the time of travelin	I tractor, since the selection gear is inappropriate and this reason, the seal is g, and in the worst case, the and high speed traveling			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
— Г <u>ј</u> г		2012~2014	14	①14台 ②14台
				③14台 ④14台
				⑤ 5台 ⑥14台
	「JD-7230R」			⑦14台 ⑧14台
	130-7230[1]	2015~2017	14	①13台 ②4台
				③14台 ④10台
				⑤ 1台 ⑥14台
				⑦ 3台 ⑧ 3台
_	「JD-7280R」		18	①18台 ②18台
		2012~2014		③18台 ④18台
		2012 2014		⑤ 1台 ⑥18台
				⑦18台 ⑧18台
_	「JD-7290R」		34	①28台 ②17台
		2014~2017		③34台 ④20台
		2014 2017		⑤ 0台 ⑥34台
				⑦ 7台 ⑧ 7台
_	「JD-7310R」		5	①0台 ②0台
		2016~2017		③5台 ④0台
		2010 92017		⑤0台 ⑥4台
				⑦0台 ⑧0台
				①73台 ②53台
		TOTAL	85	③85台 ④62台
		ITOTAL	00	⑤ 7台 ⑥84台
				⑦42台 ⑧42台