## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	4689	DATE	March 19, 2020		
MANUFACTURER	Mazda Motor Corporation				
DESCRIPTION OF	[1] On the air shutter valve, due to inappropriate control program, the valve output is not controlled correctly, a fail safe mode may not				
DEFECT	operate sufficiently when the engine warning light illuminates, and the valve may not open fully by such as the soot caught around the valve. Therefore, the engine stall may be caused when the valves are fixed with fully closed by the adhesion of the soot.  [2] On the exhaust pressure sensor of the engine, inappropriate				
	program of judgment abnormal condition, when the water intended into the inside of the sensor and output of the sensor is deviated sensor may not detect the abnormal when the exhaust gas doe meet the standard. Therefore, in continuous uses, the electric of may corrode and disconnected, the engine warning light illuminate and idling stop may not operate by the fail safe control a large shift shock may be caused.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-BM2AP	Mazda 「Axela」	2016-2018	6
LDA-BM2AS		2016-2018	36
LDA-BM2FP		2016-2018	37
LDA-BM2FS		2013-2018	199
LDA-GJ2AP	Mazda 「Atenza」	2014-2018	44
LDA-GJ2AW		2014-2018	86
LDA-GJ2FP		2012-2018	319
LDA-GJ2FW		2012-2018	313
LDA-KE2AW	Mazda ΓCX-5]	2012-2016	869
LDA-KE2FW		2012-2016	979

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-KF2P	Mazda 「CX-5」	2016-2018	948
		Total	3,836

Note: This recall campaign was submitted on November 8, 2018, assigned "4351 ①, ②" as recall number. Some affected vehicles were found to have incomplete remedy for the engine control module due to insufficient instruction of repair to correct the defect. Therefore, the recall will be newly conducted for the subject vehicles that have not completed the repair of the engine control module.