

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2585	DATE	Jul.29.2010
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the steering system of the subject vehicles, due to the improper construction of the steering shaft connection, there is a possibility that the part, which fixes the axial movement of the shaft, may disengage when the vehicle passes over a big bump. In this condition, if the steering is repeatedly turned to the locked position, the steering shaft may pull out, which could result in a loss of steering control.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-UZJ100W	LAND CRUISER WAGON	2002-2007	8,837
KR-HDJ101K	LAND CRUISER	2003-2007	841
		TOTAL	9,678