

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2693	DATE	Jan.18.2011
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Incorrect parts may have been assembled on Fuel Injection Control Unit at vehicle production process. In this case, they may not comply with noise regulation when accelerating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-CF4MA	ADDRESS V125	2010	514
		TOTAL	514