

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2704	DATE	FEB. 3 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large-sized route buses, the strength of the flywheel ring gear may be insufficient. If the engine on these vehicles is frequently restarted by the idling stop and start system, the flywheel ring gear edge may break and the engine may become unable to restart. In the worst case, broken gear pieces will get caught between the flywheel housing and the ring gear, making holes in the flywheel housing and cause oil leaks.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-MP33JK	FUSO AERO STAR	2002～2002	4
KL-MP33JM		2000～2004	122
KL-MP35JK		2000～2005	100
KL-MP35JM		2000～2005	793
KL-MP35JP		2000～2004	7
KL-MP37JK		2000～2004	351
KL-MP37JM		2000～2005	300
PJ-MP35JK		2004～2007	63
PJ-MP35JM		2004～2007	779
PJ-MP35JP		2005～2007	15
PJ-MP37JK		2004～2007	199
PJ-MP37JM		2004～2007	130
		TOTAL	2,863