

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2718	DATE	March 1,2011
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	INAPPROPRIATE INSTALLATION OF THE FUEL TUBE QUICK CONNECTOR TO THE FUEL OUTLET NIPPLE ON THE FUEL TANK COULD CAUSE INSUFFICIENT FITTING OF THE QUICK CONNECTOR. AS A RESULT, THE QUICK CONNECTOR MAY BE REMOVED FROM THE NIPPLE RESULTING IN FUEL LEAK.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GA3W	R V R	2011	2
		TOTAL	2