

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2715	DATE	March 3 ,2011
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the sightseeing buses with the fuel tank added on, it has been found that the bottom plate for the tank was inadequately configured, and therefore water deposited between the bottom face of the tank and the bottom plate, thereby causing corrosion. Thus, if they are used as are, a hole may be opened in the tank, thereby causing fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-LV774R2	GALA	2000-2005	602
KC-LV780H1		1997-2000	178
KL-LV780H2		2000-2005	125
KC-LV781N1		1997-1999	10
KL-LV781N2		2000-2001	3
KC-LV781R1		1996-2000	241
KL-LV781R2		2000-2005	146
KC-LV782R1		1996-2000	229
		TOTAL	1,534