VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2725	DATE	Ē	March 15 . 2011	
MANUFACTURER	Komatsu Utility Co. , Ltd.				
DESCRIPTION OF DEFECT	Due to insufficient durability of gear shafts because of using improper material, which is installed to front axle, shaft wear may happen. Therefore if a machine continuously used, planetary gear might be broken and a machine can not travel.				
TYPE	COMMERCIAL NAME		MODEL YEAR		NUMBER OF VEHICLE
	177.111	_	-	CALLED	VEINGEE
KDP-M250	FD35N,F	FD35N,FD40N		3~2010	14
KDP-M252	FD35,FD40,F	FD35,FD40,FD45,FD50A		3~2010	54
EBT-M251	FG4	FG40N		2009	1
			T	OTAL	69