

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2721	DATE	March 17, 2011
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	On the crank pulley equipped with engine vibration isolation rubber, certain vibration isolation rubber may peel off at adhesion surface during usage due to failures in production process. Under these circumstances, the ring (outer ring) of the affected crank pulley will idle, and engine revolution will possibly cease because the alternator will become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
UA-RC1 CBA-RC1 DBA-RC1	R2	2003~2007	27,977	
UA-RC2 CBA-RC2 DBA-RC2			10,150	
CBA-RJ1 DBA-RJ1			5,606	
CBA-RJ2 DBA-RJ2	1,566			
DBA-RN1	STELLA		36,960	
DBA-RN2			11,967	
			TOTAL	94,226