

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 7 2 6	DATE	March.24.2011
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>On certain medium duty trucks which have DPF, the ambient temperature of the air nylon tube for brake, the transmission shift cable and the parking brake cable placed near the exhaust pipe may increase. It might cause melting and making holes on some tubes and/or some cables. Then the brake force will decrease, furthermore it might cause operation failures of the transmission and the parking brake.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-LK36 series	Condor	2004~2006	88
PB-MK36 series	Condor	2004~2006	3,865
		TOTAL	3,953