

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	2727	DATE	March 29, 2011
MANUFACTURE	SUMITOMO NACCO MATERIALS HANDLING CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	On the hub of the front drive axle, there is a potential of the crack occurred because the strength is insufficient in the severe truck usage. If the truck is being used in such condition, the brake drum portion of the hub is potentially damaged. Then the brake performance is getting malfunctioned.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
G1K	FG14PX	2006	1
SG1H	FG09PX, FG10PX, FG14PX, FG15PX, FG18PX, FG20PX, FT15PX, FT18PX, FT20PX	2006 ~ 2008	84
SG1HL	FL15PX	2007 ~ 2008	3
SD1E	FD09PX, FD10PX, FD14PX, FD15PX, FD18PX, FD20PX	2006 ~ 2008	22
EDM-SD1E	FD09PXI, FD15PXI, FD18PXI, FD20PXI	2008 ~ 2010	23
EBT-SG1J	FG09PXI, FG14PXI, FG15PXI, FG18PXI, FG20PXI	2008 ~ 2010	32
EBT-SG1JL	FL15PXI, FL18PXI, FL20PXI	2008 ~ 2010	17
		TOTAL	182