## VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

## Domestic Vehicles

| 2730  | DATE  | March 31, 2011  |  |
|---|---|---|--|
| Mazda Motor Corporation   |   |   |  |
| On certain engines, due to improper setting on part assembling equipment, a clip to retain the piston pin, which holds the piston and the connecting rod, may have been deformed. When it would be used continuously as is, the clip may come off, causing a dislocation of piston pin and leading an unusual noise and damage of the piston/connecting rod subsequently. In the worst case, the engine may be damaged, resulting in an engine oil leak |   |   |  |
| o h   | lazda Motor Corporation on certain engines, due to clip to retain the piston od, may have been deformed clip may come off, canusual noise and damage worst case, the engine | lazda Motor Corporation on certain engines, due to improper setting on participation to retain the piston pin, which holds the piston, may have been deformed. When it would be ne clip may come off, causing a dislocation of pinusual noise and damage of the piston/connecti |  |

| TYPE      | COMMERCIAL<br>NAME | MODEL YEAR<br>RECALLED | NUMBER OF<br>VEHICLE |
|-----------|--------------------|------------------------|----------------------|
| DBA-GH5FP | Mazda<br>ATENZA    | 2008-2008              | 268                  |
| DBA-GH5AP |                    | 2008-2008              | 41                   |
| DBA-GH5FS |                    | 2008-2008              | 392                  |
| DBA-GH5AS |                    | 2008-2008              | 35                   |
| DBA-GH5FW |                    | 2008-2008              | 382                  |
| DBA-GH5AW |                    | 2008-2008              | 65                   |
|           |                    | Total                  | 1,183                |