

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2732	DATE	March 31 . 2011
MANUFACTURER	Komatsu Utility Co. , Ltd.		
DESCRIPTION OF DEFECT	<p>Because a safety valve is not placed in the steering valve assembly, the oil pressure of the steering cylinder might increase which is occurred by the shock of the crash , and a nut which tie up rod and piston might come loose in a steering cylinder.</p> <p>Therefore, if a machine is continuously used, in the worst case a nut might drop out and steering performance of vehicle might not be able to satisfy the safety requirement.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-WA106	WA30-6	2008~2011	16
EDM-WA106A	WA30-6	2008~2011	967
EDM-WA107	WA40-6,WA50-6	2008~2011	96
EDM-WA107A	WA40-6,WA50-6	2008~2011	1,258
		TOTAL	2,337