VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2735	DATE	March 31 ,2011
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		In the vehicles on which exhaust pipe was modified to vertical type, it has been found that a valve installed on an exhaust pipe outlet port to keep rainwater from entering was secured in an inadequate way, and therefore, the valve securing fittings may come off by exhaust pressure. Thus, if it is used as is, there is a possibility that the parts may be dropped.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
PKG-FRR90S2	FORWARD	2008	2
		TOTAL	2