VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2769	DATE	June 15, 2011
MANUFACTURE	Mazda Motor Corporation		
DESCRIPTION OF	On windshield wiper motor, the ground terminal may be bent. It may cause		
DEFECT	a loss of the electrical	ground connection, wh	ich could result in an
	inoperative wiper motor.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BK5P		2008-2009	14,374
CBA-BKEP DBA-BKEP	Mazda AXELA	2008-2009	4,315
DBA-BK3P		2008-2009	1,227
		Total	19,916