

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2765	DATE	June 21.2011
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	<p>There is the possibility that the thrust collar may be damaged with fixing the pulley, because the thrust collar strength for the pulley in turning operation transmission may not be enough.</p> <p>It may cause the machine does not turn, because the unfixed pulley may have jolt , the key groove may be wearing out and, finally, the right and left wheel may not have any speed difference by the damaged pulley.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-C43B	AJ433	2006 2007 2008 2009	678
			TOTAL 678