

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 7 7 5	DATE	J u n . 2 8 . 2 0 1 1
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the centralized ground ・ the joint connector (for grounding for the lights, such as a headlight, etc., and a horn, etc.), there is no margin in the permissible temperature of the joining terminal, some of the said connectors have been melted, which were caused by heat generation from electrification. Because of that, when grounding is not appropriately done due to a continuity defect, then the lights, such as a headlight, etc., and a horn, etc. may not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B K - S G 2 0 J	M A J E S T Y Y P 2 5 0	2 0 0 7 ~ 2 0 1 0	1 4 , 2 9 4
TOTAL			1 4 , 2 9 4