

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2843	DATE	Oct. 26, 2011
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	On dump truck vehicles, it is possible the drip of water coming from bottle or cup on cup holder seeps in the contact point of rear deck activation switch installed below the cup holder. Accordingly, the electrical circuit may possibly be short-circuited, and in the worst case, the rear deck could be tilted up wrongly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TE-S200P	HIJET	2005-2011	266	
TE-S210P			5,955	
LE-S210P				
EBD-S201P				194
EBD-S211P				7,912
		TOTAL	14,327	