

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2885	DATE	Jan.25.2012
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>On certain light duty trucks, due to improper processing location of the notches on the steering wheel boss, which are used to position the combination switch, there is a possibility that stiff stress may be applied to the wiring harness for the horn routed between the steering wheel and the switch. If the vehicle is continuously operated in this condition, the wiring harness may open circuit, which could result in the horn becoming inoperative.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADF-KDY221	DYNA TOYOACE	2009-2010	573
ADF-KDY231 ADF-KDY231 "kai"(modified)		2009-2010	1,926
ADF-KDY241V		2009-2010	36
ADF-KDY271		2009-2010	397
ADF-KDY281 ADF-KDY281 "kai"(modified)		2009-2010	1,277
ABF-TRY220		2009-2010	948
ABF-TRY230 ABF-TRY230 "kai"(modified)		2009-2010	1,669
NBG-TRY231		2009-2010	124
NBG-TRY281		2009-2010	24
		TOTAL	6,974