

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 8 9 6	DATE	Feb.16.2012
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to inappropriate assembly procedure of the stop lamp switch, the stop lamp switch may push the brake pedal. If the vehicle continues to be driven in this condition, the braking force may occur when the driver does not operate the brake pedal.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-Y12	N I S S A N W I N G R O A D	2 0 1 1	82
DBA-NY12			12
DBA-JY12			4
DBF-VY12	N I S S A N A D / A D E X P E R T		187
DBF-VZNY12			104
CBE-VAY12	N I S S A N A D		52
CBF-VJY12	N I S S A N A D E X P E R T		9
DBF-BVY12	M A Z D A F A M I L I A V A N		22
DBF-BVZNY12			2
CBE-BVAY12			2
DBF-CVZNY12	M I T S U B I S H I L A N C E R C A R G O	6	
DBF-CVY12		1	
		TOTAL	483