

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 8 9 7	DATE	Feb.23.2012
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to insufficient tightening of the fuel pressure sensor connected to the engine fuel delivery rail, there is a possibility that, the pressure sensor could loosen by engine vibration etc. Therefore, fuel may leak through the threaded portion of the sensor.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-FC26	N I S S A N S E R E N A	2 0 1 0 ~ 2 0 1 1	45,287
DBA-FNC26			6,827
DBA-C26			28,142
DBA-NC26			4,836
CBA-NF15	N I S S A N J U K E		3,725
CBA-F15			1,888
DBA-SC26	S U Z U K I L A N D Y		1,618
DBA-SNC26			356
		TOTAL	92,679