

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2902	DATE	March 1 , 2012
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	At the passenger foot step(s), certain production batches of circlip(s) may be brittle, cracking when installed on the pivot pin(s). Continued use in this condition can allow circlip(s) to separate due to engine vibration, causing the pivot pin to come out of its position. This can resulting in a separation of the step and fall off, which leads to be obstruction to the traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-EX250K	Ninja250R	2012	812
EBL-ER400B	ER-4n	2012	5
EBL-ER400B	ER-4n ABS	2012	5
EBL-ER400B	Ninja400R	2012	329
EBL-ER400B	Ninja400R ABS	2012	10
<b>TOTAL</b>			<b>1,161</b>