

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2914	DATE	Mar.9.2012
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>During the welding process of the bracket which secures the steering system to the body part, due to improper treatment for the trial parts produced for the preparation of the mass production, there is a possibility that some trial parts may be mixed in the mass production parts. In those trial parts, welds may separate when the steering wheel is turned, causing abnormal noise. In the worst case, the steering wheel may suddenly lower, which could result in the operation of the steering wheel becoming difficult.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ACA33W	VANGUARD	2007	70
DBA-GSA33W		2007	12
DBA-ACA31W	RAV4	2007	6
DBA-ACA36W		2007	2
		TOTAL	90