

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1831	DATE	April 18 th 2012
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>Due to the inappropriate insertion of the plastic lock at the insulating fixation material on battery plus cable under the luggage room floor panel, the fixing of insulating fixation material to the vehicle body may become loose because of influence such as vibration etc.</p> <p>In such case, due to poor contact and insulation failure, power supply to electrical system will not be enough, which may cause engine stall and not possible to restart. And, scorching of luggage room floor panel may occur due to localized temperature increase around battery plus cable caused by discharge between contact points. In worst case, vehicle fire might occur.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-NA25	BMW 525i	2003 ~ 2005	9,309
ABA-NE25		2005 ~ 2007	7,320
ABA-NU25		2007 ~ 2009	6,121
GH-NA30	BMW 530i	2003 ~ 2005	5,524
ABA-NE30		2005 ~ 2007	3,259
ABA-NU30		2007 ~ 2009	2,257
ABA-NB40	BMW 540i	2005 ~ 2007	359
ABA-NW40		2007 ~ 2009	232
GH-NB44	BMW 545i	2003 ~ 2005	1,191
ABA-NB48	BMW 550i	2005 ~ 2007	441
ABA-NW48		2007 ~ 2009	250
GH-NG25	BMW 525i Touring	2004 ~ 2005	1,566
ABA-NL25		2005 ~ 2007	2,171
ABA-PU25		2007 ~ 2010	2,114
ABA-NL30	BMW 530i Touring	2005 ~ 2007	869
ABA-PU30		2007 ~ 2010	592
ABA-PV30	BMW 530Xi Touring	2007 ~ 2010	113
ABA-NH48	BMW 550i Touring	2006 ~ 2007	146
ABA-PW48		2007 ~ 2009	115
ABA-EH30	BMW 630i	2004 ~ 2010	1,159
GH-EH44	BMW 645Ci	2003 ~ 2005	813
GH-EK44	BMW 645Ci Cabriolet	2004 ~ 2005	319
ABA-EH48	BMW 650i	2005 ~ 2009	1,049
ABA-EK48	BMW 650i Cabriolet	2005 ~ 2009	570
ABA-NB50	BMW M5	2005 ~ 2009	1,357
ABA-EH50	BMW M6	2005 ~ 2009	517
ABA-EK50	BMW M6 Cabriolet	2006 ~ 2009	119
		TOTAL	49,852