## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No. 2927 DATE April 19, 2012

MANUFACTURER Kawasaki Heavy Industries, Ltd.

DESCRIPTION OF DEFECT At the passenger foot step(s), certain production batches of circlip(s) may be brittle, cracking when installed on the pivot pin(s). Continued use in this condition can allow circlip(s) to separate due to engine vibration, causing the pivot pin to come out of its position. This can resulting in a separation of the step and fall off, which leads to be obstruction to the traffic.

TYPE	COMMERCIAL NAME	MODEL YEAR		NUMBER OF VEHICLE
		RECALLED		
JBK-EX250K	Ninja250R	2012		13
EBL-ER400B	Ninja400R	2012		4
			TOTAL	17