

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1837	DATE	April 23 rd 2012
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to an inappropriate manufacturing process of the housing of electric additional coolant pump for turbocharger, a crack may occur on the housing. In such case, coolant or humid can enter from the crack, which might cause short circuit on the circuit board and scorch damage of plug connection might occur. In worst case, vehicle fire may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FR44	BMW 550i	2011	11
ABA-SP44	BMW 550i xDrive Gran Turismo	2011	1
ABA-LZ44	BMW 650i Cabriolet	2011	4
ABA-KB44	BMW 750Li	2011	1
ABA-KB60	BMW 760Li	2011	2
DAA-KX44L	BMW ActiveHybrid 7L	2011	3
ABA-ZV44	X5 xDrive 50i	2011	4
ABA-GY44	X5 M	2011	5
ABA-GZ44	X6 M	2011	6
DBA-SV16	MINI Cooper S	2011	26
ABA-MFJCW	MINI CooperS JCW	2011	7
DBA-ZP16	MINI CooperS Convertible	2011	2
ABA-MSJCW	MINI JCW Convertible	2011	1
DBA-ZG16	MINI CooperS Clubman	2011	78
DBA-ZC16	MINI CooperS Crossover	2011	34
CBA-ZC16A	MINI CooperS Crossover A4	2011	31
DBA-ZC16A		2011	7
		TOTAL	223