

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN NO.	2936	DATE OF NOTIFICATION	15th.MAY.2012
MANUFACTURER	TCM CORPORATION		
DESCRIPTION OF DEFECT	<p>The transistor in the relay drive power supply circuit of the relay unit which controls lighting of lamps may generate heat because of heat dissipation deficiency in performance. If continues using it, the transistor may be damaged and it becomes impossible to turn on lamps.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
F98	TCM	2011	10
F99	TCM	2011	8
F100	TCM	2011	1
		TOTAL	19