

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2935	DATE	May.16.2012
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On the Variable Gear Ratio Steering (VGRS) system, due to inappropriate programming for the VGRS control, the steering wheel may become off-centered when restarting immediately after the vehicle is parked with the steering wheel turned, causing the aiming of the headlamp to become misaligned to the horizontal direction.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GRL10	GS350	2011-2012	375
		TOTAL	375