

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1846	DATE	May 22, 2012
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)		
DESCRIPTION OF DEFECT	Inappropriate, in terms of specification, propeller shaft has been installed so that universal joint damage and tube welding crack has been found. Propeller shaft needs to be replaced to proper one.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unspecified	FH12	2003-2007	61
Unspecified	FM12	2004	2
Unspecified	FH	2007-2009	21
		TOTAL	84