

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	Gai-1842	DATE	May 29, 2012
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	Because inner tube used in dealer optional stainless mesh brake hose is not proper, the hose may be cracked due to bent or kink. This may cause brake fluid leak and the rider may experience a reduction in brake performance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BHY	FXST	2000-2012	2
BJY	FLSTC		3
BMY	FLSTF		2
BNY	FLSTN		2
BV5	FXST		8
BW5	FLSTC		12
BWB	FLSTCI		1
BX5	FLSTF		21
JA5	FXSTB		1
JBB	FXSTDI		1
JD5	FLSTN		17
JEY	FLST		1
JK5	FXCWC		29
JL5	FXSTC		9
JM5	FLSTSB		2
JN5	FSLTFB		23
JP5	FXS		2
GEV	FXD		1
GM4	FXD		1
GN4	FXDL		23
GP4	FXDWG		28
GTV	FXDC		1
GV4	FXDC		3
GW1	FXD 35 th Anniv		1
GX4	FXDB		5
GZ4	FLD		1
		TOTAL	200