VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1848	DATE	2012/5/29	
MANUFACTURE	Daimler AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)			
DESCRIPTION OF DEFECT	During global product monitoring, Daimler AG became aware that in isolated cases, an interruption of the frictional connection may occur in the transmission on A-Class and B-Class vehicles with continuously variable transmission (CVT). The complaint generally manifests itself as noises while driving and can therefore immediately be recognized by the driver. The warning message "Transmission - Service Required" appears in the instrument cluster. The steering power and brake servo assistance remain functional, however, so that the vehicle can still be safely parked. In the worst case, if the vehicle is used under this condition continuously, the transmission belt may break and the driving force may be interrupted.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
CBA-245232	B180	2011	29
DBA-169032	A180	2011	4
		TOTAL	33