

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3001	DATE	July 20 , 2012
MANUFACTURER	komatsu Ltd.		
DESCRIPTION OF DEFECT	As for fuel injection pump of engine, some delivery guides inside of delivery holder have initial crack at sealed part due to improper thermal processing. Therefore, operating with this condition may extend the crack and cause fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-WA106AK	WA30-6	2011	117
EDM-WA107K	WA40-6,WA50-6	2011	8
EDM-WA107AK	WA40-6,WA50-6	2011~2012	96
			TOTAL
			221