

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 9 9 7	DATE	July.27.2012
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to insufficiency the strength of the air guide for the radiator, the air guide may crack by the vibration during the driving. If the vehicle continues to be driven in this condition, the air guide will break and contact to the road, in an extreme case, a part of the air guide may fall off the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
PA-AHW41	N I S S A N C I V I L I A N	2 0 0 5 ~ 2 0 1 0	1,094
PA-AVW41			523
PA-AJW41			219
PA-ACW41			20
PDG-EHW41			816
PDG-EVW41			566
PDG-EJW41			141
PDG-ECW41			12
ABG-DHW41			44
ABG-DVW41			49
ABG-DJW41			13
ABG-DCW41			3
PDG-SEHW41			I S U Z U J O U R N E Y
PDG-SEVW41	15		
PDG-SEJW41	13		
PDG-SECW41	2		
ABG-SDHW41	4		
ABG-SDVW41	1		
		TOTAL	3,571