

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3009	DATE	Jul. 31 2012
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty tractors, the plunger (a part operated by the brake pedal) in the brake valve is positioned out of center due to improper production process of the brake valve, which causes poor sliding condition of the plunger. If the vehicle continues to be used in this condition, slow returning of the brake valve due to the above problem will cause brake dragging and, in the worst case, it may result in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-FP54VDR	FUSO	2010~2012	1,117
LKG-FP54VER		2010~2012	187
LKG-FP54VGR		2010~2012	61
QKG-FP54VDR		2010~2012	224
QKG-FP54VER		2012~2012	38
QKG-FP54VGR		2010~2012	26
		TOTAL	1,653