

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2971	DATE	July 13.2012
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	As of traveling device, track roller axles used in setup of track roller and equalizer under chassis may break at their edge, due to improper thermal processing. Keeping operation as it is may deteriorate clamping force in these setups and let them come off. In the worst case, it may lead the unit disable to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	AG460	2012	7
	AG470	2012	8
	AG572	2012	15
TOTAL			40