

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|---|------|----------------|
| CAMPAIGN No. | GAI-1864 | DATE | August 23 2012 |
| MANUFACTURE | Triumph Motorcycles Limited (Japanese Importer : Triumph Japan K.K.) | | |
| DESCRIPTION OF DEFECT | Voltage regulator overheating occurs due to high ambient temperatures and a lack of airflow. When that happens, the voltage regulator function goes down or lose. This ultimately results in the battery being drained as it is not being re-charged as the engine is running. And the engine will stop and can not start up again. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|-----------------|---------------------|-------------------|
| SMTTMD10 | Daytona 675 | 2006 - 2009 | 515 |
| SMTTMD106 | Daytona 675 | 2009 - 2011 | 278 |
| SMTTMD406 | Street Triple | 2008 - 2011 | 327 |
| SMTTMD416 | Street Triple R | 2009 - 2011 | 155 |
| | | TOTAL | 1,275 |