

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2976	DATE	August 23,2012
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	There may have been a manufacturing failure in the fuse of the traction battery (soldered portion in the fuse is inappropriate). If use continues under this condition, the subject fuse would be blown out causing the traction motor to be stopped, which could result in the vehicle unable to be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-HA3W	i-MiEV	2009	810
		TOTAL	810