

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3011	DATE	August 24 ,2012
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		The weld strength of the heat protector mounting portions of silencers in some outside broadcast vans is insufficient, and the welded portions may have cracks due to automotive vibration, etc. during driving. The cracks will eventually propagate as the vans continue driving. In extreme cases, the heat protectors may fall down	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-NPS85ANKAI	ELF	2008 - 2008	7
SDG-NPS85ANKAI		2011 - 2011	6
		TOTAL	13