

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1865	DATE	August 28 th 2012
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing of part of a component of the circuit board of control module for electric power steering, defect occurs on the circuit board. In this case, warning lamp (decrease of power assist) may light on, power-assisted steering will be suddenly deactivated and stronger power is needed to steer the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LBA-UC20	BMW 120i Coupe	2011	1
LBA-US20	BMW 320i Touring	2011	7
LBA-KD20	BMW 320i Coupe	2011	1
DBA-LL20	BMW Z4 sDrive 20i	2011	13
ABA-LM30	BMW Z4 sDrive 35i	2011	1
ABA-LM35	BMW Z4 sDrive 35is	2011	1
		TOTAL	24