

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3017	DATE	August 30 ,2012
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>The mechanical automatic transmission, mounted in each type of the mid-duty trucks indicated, has improper clips used to fix both the ends of the oil hose onto the pipe. The clips have too strong tightening effect, excessive stress may be applied to the oil hose, which may result in generation of cracks in the hose. If the use of the oil hose is continued under this condition, oil leak will occur and if things go wrong, the vehicle will be out of order.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
PDG-FRR34S2 PDG-FRR34T2	FORWARD	2007-2011	956	
PKG-FRR90S1 PKG-FRR90S2 PKG-FRR90T2 SKG-FRR90S2		2007-2011	4,380	
PKG-FSR34S2 PKG-FSR34T2		2007-2011	298	
PKG-FSR90S2 PKG-FSR90T2 SKG-FSR90S2		2007-2011	268	
PDG-FTR34S2 PDG-FTR34T2 LDG-FTR34S2 LDG-FTR34T2		2007-2011	500	
LKG-FTR90S2 LKG-FTR90T2		2010-2011	76	
PDG-FVR34U2 LKG-FVR34U2		2007-2011	102	
		TOTAL		6,580