

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN	3064	DATE	November 27, 2012
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	On the trucks with gasolin engine, it has been found that battery cable may interfere with the coolant connector of engine due to the small clearance of them. Therefore, this interference may cause the damage of the cable by the engine vibration and the consequent fire in worst case if the truck is operated under such conditions.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBT-J1F4	N I S S A N F O R K L I F T	2 0 0 9	1
		TOTAL	1