

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3046	DATE	Oct. 24, 2012
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>Because of the unsuitable water drain structure in slide door lock of luggage box, water is trapped inside the door lock during washing car, etc. and this may cause the rust formation.</p> <p>With this condition, there is possibility that the door lock is stuck at open state when opening the slide door and the slide door is kept unlocked.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S201P	HIJET	2008-2010	1,291
EBD-S211P			416
		TOTAL	1,707