

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3032	DATE	October 4, 2012
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	<p>The hydraulic pump which have incorrect connection is equipped on agricultural tractor.</p> <p>The operation pressure of the pump goes higher, the gear-plate (pump chamber) gets out from their alignment. Then discharge quantity of the pump decreases due to seizure on a bearing of input shaft.</p> <p>If this pumps are continued to use under such condition, the hydraulic pressure which controls hydraulically clutch of transmission and assists power steering may not work correctly. It may cause a weaken drive or much larger force of operation to steer to be needed. In the worst case, in put shaft might be broken and the tractor might get difficulty of steering or/and drive.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-T165F	TJW107	2008—2012	127
EDR-T166F	TJW117	2008—2012	494
TOTAL			621