

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2143	DATE	January 28, 2015
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper production for acceleration sensor of Airbag control unit, Airbag warning light turn becomes active. In such case, Front airbag, Side airbag, and Curtain airbag become inactive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-6RCJZ	「VW Polo 1.2/66kW」	MY2015	1,072
DBA-6RCZE	「VW Polo Blue GT/110kW」	MY2015	55
		Total	1,127