

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	3506	DATE	January-28-2015
MANUFACTURER	PABCO CO.,LTD		
DESCRIPTION OF DEFECT	For rear top marker lamps are mounted on the upper rear part of Banbody, there is mounting position is inappropriate. Therefore, the upper viewing angle of the rear top marker lamp has become incompatible with the safety standards.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBF-FB700B	FUSO CANTER	2007	1
PA-FB70BB		2006	2
PA-FD70BB		2006	1
PA-FE70BB		2006	3
PA-FE70DB		2006	2
PA-FE82DE		2006	1
PDG-FB70B		2007	1
PDG-FE70B		2007 ~ 2009	2
PDG-FE72D		2008	1
SKG-FBA00		2011	1
SKG-FBA20		2012	1
SKG-FEA50		2011	1
SKG-FEB90		2011	2
TKG-FBA20		2013	3
TKG-FBA50		2013	1
TKG-FDA20		2012	1
TKG-FEA50		2013 ~ 2014	2
TPG-FBA00		2012	2
PB-NKR81AN	ELF	2006	4
SKG-NJR85		2012	1
TKG-NJR85AN		2013	1
TKG-NPR85AN		2013	1
BDG-XZU504M	HINO DUTRO	2008	1
BDG-XZU508M		2007	2
BJG-XKU508M		2007	1
BKG-XZU538M		2008	1
PB-XZU301M		2005	1
TKG-XZU605M		2012 ~ 2013	9
		TOTAL	50