VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3509	DATE	Jan. 29 2015		
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation				
DESCRIPTION OF DEFECT	stay was assemble mounting bolts at t may crack due to th	On some heavy-duty sightseeing buses, the manually-foldable left mirror stay was assembled improperly, which caused weak axial tension of the mounting bolts at the mirror-side stay. Because of this, the mirror-side stay may crack due to the vibration during running, etc. If the bus continues to be used in this condition, the cracks will develop and, in the worst case, the left			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-MM96FH		2008 ~ 2011	9
SDG-MM96FH	「FUSO AERO ACE」 -	2011	1
QDG-MM97FH		2014	1
BKG-MS96JP		2007~2010	384
	「FUSO AERO QUEEN」	2007~2010	11
LKG-MS96VP		2010~2012	123
QRG-MS96VP	- 「FUSO AERO ACE」	2012~2014	305
	「FUSO AERO QUEEN」	2012~2014	8
PDG-AM96FH	- 「SPACEARROW A」	2009	1
BKG-AS96JP	- SFACEARROW A]	2008~2010	24
		TOTAL	867