VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3503	DATE	February 19, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	strength insid end door latch manufacturing operation can unlock functi	e the front door due to improp g. Therefore r break the part r	et only with insufficient latch and/ or the rear er material used in the epetitive lock/ unlock resulting in unable lock/ orst case the vehicle doors.

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	
HBD-DA64V			12,600	(1)12,184 (2)7,353
EBD-DA64V	EVERY		5,200	(1)5,036 $(2)2,379$
ABA-DA64W			3,411	①3,323 ②1,636
EBD-DA16T	CARRY	9014	1,902	1
HBD-DR64V	NV100	2014	4,709	①4,549 ②2,611
EBD-DR64V	CLIPPER		1,076	①1,058 ②359
ABA-DR64W	NV100 CLIPPER RIO		839	(1)813 (2)434
EBD-DR16T	NT100 CLIPPER		343	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES		
HBD-DG64V		2014	989		①964 ②416
EBD-DG64V	CCDIBA		461	①447 ②230	
ABA-DG64W	SCRUM		226	$ \begin{array}{c} 1220 \\ 2113 \end{array} $	
EBD-DG16T			31	1	
HBD-DS64V	MINIGAR		1,084	①1,050 ②517	
EBD-DS64V	MINICAB		540	①524 ②264	
ABA-DS64W	TOWNBOX		288	$ \begin{array}{c} 1281 \\ 2128 \end{array} $	
EBD-DS16T	MINICAB		391	1	
		TOTAL	34,150	①33,116 ②16,440	

The part applied to an unknown vehicle because it was shipped as one of service parts (1)

Part Name	Part No.	Shipment Period of the part	Quantity
Front Door Latch Right	82201-68H11		136
Front Door Latch Left	82202-68H11	2014	170
Front Door Latch Right	82201-82M10		17
		TOTAL	323

The part applied to an unknown vehicle because it was shipped as one of service parts (2)

Part Name	Part No.	Shipment Period of the part	Quantity
	82510-68H02		200
Back Door Latch	82510-68H12	2014	74
	82510-73H0V		30
		TOTAL	304