

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 5 1 9	DATE	F e b . 1 7 . 2 0 1 5
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As the strength of the stay of the horn is insufficient, a load may be applied on the said stay and that may cause cracks to be developed due to a vibration occurring in the specific engine rotating area. Therefore, if it is used continuously, the cracks may progress. In the worst case scenario, the said stay may be damaged and the horn may fall off from the mounting section.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B K - V G 0 5 J	X V S 2 5 0 D r a g S t a r	2 0 0 8 ~ 2 0 1 5	8 , 1 0 7
TOTAL			8 , 1 0 7